



January 23, 2006
Project A08-21

Mr. Corey Walsh
Regional Water Quality Control Board
Central Coast Region
895 Aerovista Place, Suite 101
San Luis Obispo, CA 93401-7906

Re: Results of Well Destruction, Chalk Mountain Liquor, Atascadero, CA, APN#056-201-030.

Dear Mr. Walsh:

HerSchy Environmental, Inc. is pleased to present this report summarizing the abandonment of five monitoring wells at the above referenced site. The site is located at 9990 El Camino Real, Atascadero, California (Figure 1). The site has undergone underground storage tank replacement and subsequent installation of five groundwater monitoring wells. The site has been approved for case closure by the California Regional Water Quality Control Board, and the destruction of all monitoring wells is a condition for closure. The board has furthermore requested submission of this well destruction report by January 30, 2006.


WELL ABANDONMENT PROCEDURES

On January 19, 2006, all five groundwater monitoring wells related to the site (MW-1 through MW-5) were abandoned. The monitoring wells were abandoned by a licensed well driller under the supervision of a geologist from HerSchy Environmental, Inc. following well destruction guidelines found in Chapter 8.40 of the San Luis Obispo County Code, and in the California Department of Water Resources Bulletin #74-81. All of the wells were constructed with two-inch diameter well casing in eight-inch diameter boreholes. Depth of each well was approximately 17.5'. Using a grout pump and a dedicated hose, each well was filled to the surface with a cement-bentonite grout. Using a truck-mounted drill rig equipped with hollow stem augers, the boreholes were then drilled out to five feet below ground surface. Once over-drilled, the boreholes were backfilled with type II neat cement and then dyed to match well surroundings.



All investigative and corrective action activities at the site are now complete. No further work at the site will be performed. HerSchy Environmental, Inc. would like to thank you for your cooperation and assistance throughout this investigation.

If you have any questions or require additional information, please contact us at the letterhead address or at (559) 641-7320.

With best regards,
HerSchy Environmental, Inc.



Ed Kaczmarek
Geologist



James S. Olbinski
Senior Project Geologist
Registered Geologist #4274

pc: Mr. Roy Saunders, Jaco Oil Company
Mr. Michael Hawkins, Property Owner
Ms. Sarah Wilcoxson, San Luis Obispo County Division of Environmental Health
Services

FIGURE
1